

Work Order Job # Phase	Service Location/ Comments	Call Type / Problem / Contact	Status / Pay By	Scheduled Start Time / End Time	Priority /	Est. Hours
101 - Robert E Jones						
5/18/2001						
23159	Dankwardt Swimming Pool 313 Dankwardt Drive Newburg, OR91235 Fill pipe cracked.	Plumbing Pipe Leaking Bill Hanson (503) 531-9856	8:48:08AM Opened BillOut	8:00:00AM 11:00:00AM	High	3.00
Total Hours for 5/18/2001						3.00
5/28/2001						
23158	Dankwardt Swimming Pool 313 Dankwardt Drive Newburg, OR91235 Main water pump appears to not be working - as if there was no power.	Electrical Outdoor Unit Not Running Mrs. Handy (503) 531-9856	8:46:32AM Opened BillOut	9:00:00AM 12:00:00PM	High	3.00
Total Hours for 5/28/2001						3.00
8/4/2006						
23188	ALLState University 1818 Oak Portland, OR97623 Go up ladder on east side of building, unit is 1st you come to.	Agreement Outdoor Unit Not Running Steve Baker (503) 555-1425	8:35:00PM Opened Check	1:00:00PM 4:00:00PM	High	3.00
23190	ALLState University 1818 Oak Portland, OR97623	Service Circuit is out Steve Baker (503) 555-1425	5:40:28PM Opened Check	11:00:00AM 12:00:00PM	High	1.00
23191	ALLState University 1818 Oak Portland, OR97623	Installation Installation Steve Baker (503) 555-1425	9:19:59AM Opened Check	8:00:00AM 11:00:00AM	Normal	3.00
Total Hours for 8/4/2006						7.00
9/19/2006						