

Timberline - Service

Service Work Order

P.O. Box 728
9600 SW Nimbus
Beaverton, OR 97008

Number:	23169
Entered:	5/12/2001

Duplicate

Service: ALLState University
Location: 1818 Oak
ALLST Portland, OR 97623

Alt. #:
Map:
Fax:
Cell:

Bill To: ALLState University
1818 Oak
Portland, OR 97623

Payment Expected by: Check
PO Number:

Contacts: Steve Baker (503) 555-1425
Gina Baker

Permission Code:
Call Type: Service
Problem: Circuit is out
Est. Hours/Priority: 5.00 High
Scheduled: 5/16/2001 Black; Donald M

Comments:
Admin building. Basement

Equip:
Location:

Parts:	Labor:

Comments & Notes: _____

Customer Notes:

- To Do Items:**
- A/C clean and Charge**
 - Check for leaks - A/C clean and Charge
 - Replace Filter - A/C clean and Charge
 - Replace coolant - A/C clean and Charge
 - Check Pressure - A/C clean and Charge
 - Electrical Inspection**
 - Check outlets - Electrical Inspection
 - Test Amperage - Electrical Inspection
 - Check Breaker box - Electrical Inspectio